

Temperture Convertion Chart

Celsius	Fahrenheit	Kelvin	Rankine
-273.15	-459.67	0	0
-263.15	-441.67	10	18
-253.15	-423.67	20	36
-243.15	-405.67	30	54
-233.15	-387.67	40	72
-223.15	-369.67	50	90
-213.15	-351.67	60	108
-203.15	-333.67	70	126
-193.15	-315.67	80	144
-183.15	-297.67	90	162
-173.15	-279.67	100	180
-163.15	-261.67	110	198
-153.15	-243.67	120	216
-143.15	-225.67	130	234
-133.15	-207.67	140	252
-123.15	-189.67	150	270
-113.15	-171.67	160	288
-103.15	-153.67	170	306
-93.15	-135.67	180	324
-83.15	-117.67	190	342
-73.15	-99.67	200	360
-63.15	-81.67	210	378
-53.15	-63.67	220	396
-43.15	-45.67	230	414
-33.15	-27.67	240	432
-23.15	-9.67	250	450
-13.15	8.33	260	468
-3.15	26.33	270	486
0	32	273.15	491.67
6.85	44.33	280	504
16.85	62.33	290	522
26.85	80.33	300	540
36.85	98.33	310	558
46.85	116.33	320	576
56.85	134.33	330	594
66.85	152.33	340	612
76.85	170.33	350	630
86.85	188.33	360	648
96.85	206.33	370	666
100	212	373.15	671.67
106.85	224.33	380	684
116.85	242.33	390	702
126.85	260.33	400	720
136.85	278.33	410	738
146.85	296.33	420	756
156.85	314.33	430	774
166.85	332.33	440	792
176.85	350.33	450	810
186.85	368.33	460	828
196.85	386.33	470	846
206.85	404.33	480	864
216.85	422.33	490	882
226.85	440.33	500	900
236.85	458.33	510	918
246.85	476.33	520	936
256.85	494.33	530	954
266.85	512.33	540	972
276.85	530.33	550	990
286.85	548.33	560	1008
296.85	566.33	570	1026
306.85	584.33	580	1044
316.85	602.33	590	1062
326.85	620.33	600	1080
336.85	638.33	610	1098
346.85	656.33	620	1116
356.85	674.33	630	1134
366.85	692.33	640	1152
376.85	710.33	650	1170
386.85	728.33	660	1188
396.85	746.33	670	1206
406.85	764.33	680	1224

